The Mar Project

Recommendations (Lobo Ecology)

Opportunity	Detail	Proposal	Ongoing	Work Up Y/N
SW1	Himalayan Balsam and New Zealand Pygmyweed	Curtail Spread / Remove	Manage	
SW2	No surface water run off to The Mar from New Development		Manage	
SW3	Understand nutrient status of The Mar	A study	Monitoring	
SW4	Understand Water Levels over time	Install a level	Monitoring	
SW5	New Pond Creation to the North	Sensitive Excavation		
SW6	Silt Removal	Sensitive Excavation		
SW7	Monitoring of water levels for benefit GCN population		Monitoring	
WS1	Reduce extent of Willow Scrub	Removal / Coppicing	Manage on a rotational basis	
AG1	Wildflower Planting	Establish wildflower meadow	Manage	
HR1	Hedgerow Restoration	Planting		
HR2	Hedgerow Bottom Planting	Planting		
W1	Woodland Management	Selective felling / Ring-barking		
W2	Himalayan Balsam	Balsam pulling to remove	Manage	
Bat 1	Increase Bat roosting opportunities	Erect bat boxes around the Mar and wider in the village on properties	Manage	
Bat 2	No Artifical Light to detriment of bat environment		Manage	
Bird 1	Bird Hide	Build a bird hide	Manage	
Bird 2	Bird boxes	make and install bird boxes		
Footpath	Footpath to Mar Head Balk	Formalise/Improve		

Recommendations (WSP)

Opportunity	Detail	Proposal	Ongoing	Work Up Y/N
1	Rebuild Outfall	Rebuild collapsed outfall with weir boards or stop logs		
2	Limited Silt Removal	Minor works to pond including scrapes or limited alterations to silt levels or limited new excavations		
3	Improve water supply	Install lined channel or pipe connecting field drain to north east with The Mar		
4	Improve water supply	Ensure second field drain discharges into an area of water		
5	Water level recording	Install water level measuring pole		
6	Improve water supply	Re-direct roof drainage locally to The Mar	Monitor	
7	Improve water supply	New development should consider utilising The Mar for surface water discharge	Monitor	
8	Improve water supply	Investigate West Field Lane drainage		